


Index File No. 45 R. 9W Tract or Survey No. I-5
 Merid. Will. R.D. HEBO County TILLAMOOK # 708
 N.F. SILUSLAW State ORE

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND
 PIPE 18" ABOVE GROUND IN GOOD CONDITION.
 THIS CORNER WAS RESTORED BY M. WHITMORE 5-17-52

DESCRIBE BEARING-TREES OR OTHER OFFICIAL ACCESSORIES FOUND
 FOUND 30" FIR, N.33°E, 41 LKS. WITH ORIG. MARKS 1/4 SBT

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 Signature _____

(over)
 DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER
 4-29-69 I FOUND M. WHITMORE'S PIPE & WITNESSES

PLANE COORDINATE POSITION DATA

State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
 Signature _____
 Agency _____

RECORDED.
 VISIBLE MKS "1/4 S" ON A FALLEN SHELL OF THE GLO. NE
 T RED PAINT ON FACES AND AROUND WITNESSES,
 L. Whitmore, Forestry Tech

Title _____ Division _____ Headquarters _____ Date 1-23-67
 7100-52 REV. 65 5

CORNER ORD (PERPETUATION)
 MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

ACCESSORIES: DESCRIBE NEW BT'S, WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

2 BT'S BY M. WHITMORE 1952
 15" FIR, N.75°E, 12 LKS. MKD. 1/4 SBT
 16" FIR, S.69°W, 7 LKS. MKD. 1/4 SBT

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS

Tract or Surv. No. _____ Cor. _____