

1. T4S R9W No. X-13 Cor. 7 Mer. Will. State. ORC. N. F. SIVSALW Dist. ACB0

2. Corner Status

3. Original Description Vol. Page Where Recorded

4. Description of Corners:

5. Investigation Notes:
 FIND 4"x4" ROTTED POST LYING UPON THE GROUND.
 FOUND 36 IN. SNAG, S. 30° E, 67 LKS. WITH MKS. 1/4 S BT.
 FOUND 50 IN. SNAG, S. 40° W, 4 LKS. WITH ALL MKS. ROTTED OFF

7. Photo Identification
 Photo No.
 Ident. By:

8. Plane Coordinate Position Data
 State Zone
 X
 Y
 Estab. By
 Field Book No.
 Where Filed:

9. Evaluation
 Authentic
 Needs Verif. Monument
 Re-estab. Survey
 Land Status

6. Signed L. WHITMORE Title FORESTRY TECH Date 2-23-63

PERPETUATION RECORD

11. Accessories

12. Set By: _____ Title _____
 Listed _____ Agency _____ Date _____

13. Recorded By: _____ Volume _____ Page _____
 (Agency) _____
 (Date) (City) (County) (State)

14. Remarks:
 SET 4"x4" VINEMABLE POST 36 IN. ABOVE GROUND MKD. S33 ON W. AND S34
 ON E. FACES.
 NEW BT'S
 2 1/2 IN. FIR, N. 45° W, 85 LKS. MKD. 1/4 S33 BT.
 2 1/2 IN. FIR, S. 50° 30' E, 107 LKS. MKD. 1/4 S34 BT.

IN THE PRESENCE OF:
 F. JOHNSON
 D. WHITMORE
 M. WHITMORE