

Index

File No. E-1

**CORNER RECORD (SEARCH)**

(Ref. FSM 7151.4)

Tract or Survey No.

Cor. No. #949 SC

T 6S R. 8W

R.D. Hebo

County Tillamook

Tillamook

Merid. Willamette


N.F. Siuslaw

State Oregon

Oregon

**CORNER DIAGRAM**

T6S R8W



**DESCRIBE CORNER MONUMENT FOUND**

1" galvanized pipe with 4" x 4" white post 1 ft. N

**DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND**

36" Fir stump bears N 77° 45' E 125.4 ft. with scribe marks

"T6S R8W S6 BT" showing

The SE Bearing Tree is stump

The NW Bearing Tree is missing

16" Fir bears N 21° E 23 ft. to side center

22" Fir bears S 20° E 14 ft. to side center

**PHOTO IDENTIFICATION DATA**

Photo No. \_\_\_\_\_

Filed At. \_\_\_\_\_

Object Ident. \_\_\_\_\_

Ident. By \_\_\_\_\_

Signature

X \_\_\_\_\_

Y \_\_\_\_\_

Estab. By \_\_\_\_\_

Agency

**DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH COR**

Corner is located 112 ft. North of logging road.

Signature

Title

Division

Headquarters

Date


10/29/75

7100-52 (3)

**CORNER RECORD (PERPETUATION)**

**MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT**

Set 2" galvanized pipe with 3" brass cap 6" above ground



**ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE**

Placed 1" galvanized pipe in hole on North side of monument

Set steel post with Attention sign 2 ft. South of monument

Painted 6" red band and faces of blazes on witnesses

Placed Attention signs on backs of bearing trees

Work Done By Frank L. Hall

Title Engineer

Date 10/29

State Registration No. or Agency

PE 1956

Certified Cor. Record Prepared? Yes  No

Filed At

1975

Date

**REMARKS**

Index File No. E-1

T. 6S

R. 8W

W. M.

Tract or Surv. No.

Cor.