


Index File No. C-5		CORNER RECORD (SEARCH) (Ref. FSM 7151.4)		Tract or Survey No. _____		Cor. No. _____	
T. 65 R. 9W		R.D. HeBo		County TILLAMOOK		# 962	
Merid. Will.		N.F. SILSLAW		State ORE.			
CORNER DIAGRAM		DESCRIBE CORNER MONUMENT FOUND GLO 1908 SET POST 4 M					
		16" SPRUCE, N. 62° 15' E, 14 LKS. 12" FIR, S. 21° W, 18 LKS.					
PHOTO IDENTIFICATION DATA		DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND					
Photo No. _____		FOUND 1/2" PIPE ALONGSIDE OLD ORIGINAL POST 4					
Filed At. _____		24" KETTED AND POOR CONDITION.					
Object Ident. _____		LOGGING HAS APPARENTLY DESTROYED THE ORIGINAL					
Ident. By _____		M. WHITMORE, 1958 FOUND SCRIBE MARKS ON ORIGINAL POST.					
Signature _____		DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER					
PLANE COORDINATE POSITION DATA		CORNER IS UNDER EAST EDGE OF A LOG. A.C.R. IS ABOUT 100 FT. NORTH. LOG ROAD IS 200 FT. WEST					
State _____ Zone _____		Signature Leonard Whitmore		Title Forestry Tech		Division Timber	
X _____		Headquarters HeBo		Date 8-22-73		7100-52 (3)	

CORNER RECORD (PERPETUATION)			
MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT			
Set 1/2" Pipe			
ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE			
SCRIBE 2 New BT's;			
3" DOUBLE HEM., N. 22° E., 12 ³ / ₄ FT. SCRIBED 1/4 55 BT		DISTANCES ARE TO SIDE-CENTER, VAR. 21°	
9" HEM., N. 35° W., 17 FT. SCRIBED 1/4 36 BT			
Leonard Whitmore, Tillamook County Deputy Surveyor.			
Work Done By _____	Title _____	Date _____	State Registration No. or Agency _____
Certified Cor. Record Prepared? Yes _____ No _____	Filed At: _____	Date _____	
REMARKS			
Index File No. T. 65 R. 9W M. _____ Tract or Surv. No. 41 Cor. 6 5			